



# C-AD ACTIVITY MAY 2017



## C-AD ACTIVITY

# JUNE 2017



# INTEGRATED FAILURES (GREATER THAN ONE HOUR) BY SYSTEM JUNE 2017

ESHQ

1002 Smoke detector

EBIS

Power supply and Vacuum problems

Human Error

Noise made operators skeptical of Correct Tune measurement

Rf\_AGS

L10 Power Amplifier, and assorted trips

PPS\_AGS

A5 kicker – fine delay timer replaced

Rf\_Booster

B3 power amplifiers

PS\_Booster

BMMPS filter resistor

Controls Hardware RHIC

cfe-4b-rtdl, permit hardware(?), cfe-7c-qd1,

cfe-2a-bcm, cfe-4b-qd1

Rad Mon Pulls Permit


6X

Cryo RHIC

Lead flow faults alcove 5C

Rf\_RHIC

BA2, BS2, YS3, Y&B landaus,



# Run17 availability

